A second	Hits	Search Text
1	6	"image frame synchronization".ti.
2	0	gong.in. and jin-sheng.in. and realtek.as.
3	11995	scan\$5 adj3 converte\$4
4	105142	clock near3 frequenc\$4
5	56537	adjust\$4 near4 "same"
6	0	S50 same S51 same S52
7	0	(S50 and S51 and S52).ab.
8	7	(S50 same S51).ab.
9	73	(S50 same S51)
10	15	S50 and S51 and S52
11	2382727	clock\$4 frequenc\$4
12	0	(S50 and S58 and S52).ab.
13	0	(S50 same S58 same S52)
14	113	(S50 and S58 and S52)
15	18	(S50 and S58 same S52)
16	1295	ppl
17	12001	scan\$5 adj3 converte\$4
18	0	S63 same S64
19	20815	pll
20	99	S63 same S66
21	25	S64 same S66

	DBs	Time Stamp	Comments
1	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2005/11/07 13:51	
2	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2005/11/07 13:56	
3	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2005/11/08 06:26	
4	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2005/11/07 14:31	
5	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2005/11/07 13:59	
6	USPAT	2005/11/07 14:00	
7	USPAT	2005/11/07 14:32	
8	USPAT	2005/11/07 14:00	
9	USPAT	2005/11/07 14:00	
10	USPAT	2005/11/07 14:00	
11	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2005/11/07 14:31	
12	USPAT	2005/11/07 14:32	
13	USPAT	2005/11/08 06:26	
14	USPAT	2005/11/07 14:33	
15	USPAT	2005/11/07 14:35	
16	USPAT	2005/11/08 06:27	
17	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2005/11/08 06:27	
18	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2005/11/08 06:27	
19	USPAT	2005/11/08 06:27	
20	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2005/11/08 06:28	
21	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2005/11/08 06:28	

	Error Definition	Errors	Ref #
1			S35
2			S36
3			S50
4			S51
5			S52
6			S54
7			S55
8			S56
9			S57
10			S53
11			S58
12			S59
13			S61
14			S60
15			S62
16			S63
17			S64
18			S65
19			S66
20			S67
21			S68